





Product Description: Extension Pole Attachment
Model Number: EP7501
Body Number: 2825084002_S
Version: A
Issue Date: 2016/12/05





Repair Parts_Tube Assembly_Spare parts(EP7501)

Index No.	Art. No.	Description	QTY in machine	Weight (g)	Size LxWxH (mm)	MPQ	Repairable or Not?	Standard Repair Time (min.)
1	5620549001	Hexagon Socket Screw	1	4	M5x8	10	Y	5
2	3126854001	Cover	1	2.8	34.6x22.4x6.7	1	Y	5
3	3421869001	Button	1	13.7	56.3x22x17	1	Y	5
4	3660235001	Spring	1	2	7.9x10.5	10	Y	10
5	2824788001	Joint Assembly	1	195.3	153x57x54	1	Y	10
6	3700233001	Washer	1	2	6.1x16x0.5	10	Y	5
7	3402816001	Joint Assembly	1	22.2	M6x63x25	10	Y	5
8	5620550001	Hexagon Socket Screw	1	6.5	M6x25	10	Y	1
9	3705464001	Limit Chute	1	2.8	6.4x15.4x2.5	1	Y	5
10	3128580001	Bush	1	5	φ25x36	1	Y	5
11	3128734001	Sleeve	1	4.6	φ29x42	1	Y	1
12	3128556001	Guiding Block	1	4.3	33x26x24.5	1	Y	1
13	2825082002	Tube Assembly	1	207	φ25x700	1	Y	5
14	2824782002	Shaft Assembly	1	257	φ25x742	1	Y	7
15	3706123001	Sheath	1	8.2	φ32x200	1	Y	5