



Repair Parts_Blower_4716 (LB7650E)

Index No.	Art. No.	Description	QTY in machine	Weight (g)	Size LxWxH (mm)	MPQ	Repairable or Not?	Standard Repair Time (min.)
1	3680196001	Magnet Ring	1	18	16x16x28	10	Y	15
2	5650519001	Rubber Gasket	4	2.4	20x9.9x8.9	10	Y	20
3	2828754001	Ducted Set	1	525	146x146x260	1	Y	25
4	3660088003	Knob-reset Spring	2	0.2	6x6x18	10	Y	15
5	2828460002	Blow Tube Assembly	1	298	94x94x484	1	Y	1
6	5610274003	Self Tapping Screw	1	0.8	5.6x5.6x18	10	Y	0
7	5610294001	Tapping Screw	15	1.3	7x7x18	10	Y	0
8	3132552001	Fan Baffle	1	80	169x166.5x78	1	Y	20
9	5620176002	Screw With Washer	2	3	6x6x7.5	10	Y	20
10	3660818001	Compression Spring	1	3.4	41x11x11	10	Y	15
11	3131427001	Sliding Block	1	9.7	42x41x20	1	Y	15
12	2831131001	Electric Assembly	1	200	100x80x50	1	Y	25
13	3127498001	Power Pack Button	1	9.5	43x36.8x27.5	10	Y	15
14	3127497001	Power Pack Button	1	5	42.5x24.5x11.4	10	Y	15
15	3660013003	Spring1	1	1	9.9x9.9x25	10	Y	15
16	3706375001	Hook	1	10.5	37x31x20	10	Y	1